



Rushington Business Park
Totton
Southampton
SO40 9AH
England
Tel: 023 8066 6685
Fax: 023 8066 6880
Email: info@totton-pumps.com
Website: <http://totton-pumps.co.uk>

TECHNICAL BULLETIN

Technical Bulletin Number: TB108
Originator: Chris Harrison
Customer: Various
Serial Numbers: Various
Product Affected: All GP & NEMP25/5, 28/11, 35/6, 40/6, & 50/11
Start Date: tbc
Date of Issue: 02 November 2006

Nature of Change:

To replace two-piece pump body with single piece pump body.

Reason for Change:

Previous mouldings have become unusable due to wear of the mould tool. Improved reliability of single-piece pump body due to elimination of one leak path.

Details of Change

Pump body part no. 036353 is to be replaced with pump body LH 3/8" BSP made from 016304

Pump body part no. 036354 is to be replaced with pump body RH 3/8" BSP made from 016305 (use on single ended pumps.)

This will mean that the above mentioned pumps will only be available with parallel inlet and outlet ports which will effect the following pumps:

NEMP28/11: Part no.: 186968

NEMP50/11: Part no.'s: 216949,186976,186938,486938 & 216950

It will also affect the following pump with plain ports:

GP40/6: Part no.: 216997

Note

The inlet and outlet ports of the single piece pump body are parallel whereas the outlet port of the two-piece pump body is 10 degrees off vertical.

The single piece pump body does not have the facility for orientating the inlet and outlet ports independently.