



ITT

Unit 11, Victory Park
Solent Business Park
Whiteley
PO15 7FN
England
Tel: 01489 563470
Fax: 01489 563471
Email: info@totton.com
Website: <http://totton-pumps.co.uk>

TECHNICAL BULLETIN

Technical Bulletin Number: TB124
Originator: Chris Harrison
Customer: Various
Serial Numbers: Various
Product Affected: NEMP20/12 & NEMP20/18
Date of Introduction: Immediate
Date of Issue: 22 nd July 2010

Nature of Change:
Change in colour of PPS material colour.

Reason for Change:
Due to World wide shortage of PPS and to allow production to continue.


Details of Change

Due to the shortage, the supplier of parts made in Torelina PPS can only supply in a natural (brown) colour instead of the original black colour.

The parts affected are the 016397 – front cover 15 mm plain port & 016395 stage elements. Both parts are used on pump models NEMP20/12 & NEMP20/18. Please note that the material is exactly the same it is only the colour that has changed.

For identification (from following exploded drawings on following page):
Front cover: Item 21 (NEMP20/12) & Item 20 (NEMP20/18)
Stage element: Item 16 on both NEMP20/12 & 20/18

NEMP20/12:



NEMP20/18:

